



Photo S10(A)-1 – June 2007 (upper left)
Facing north across the site. The recent overlay has obscured any recent cracking and settlement in the road surface. See Photo S10(A)-2 for a view of the site as it appeared during the 2005 inspection.



Photo S10(A)-2 – June 2005 (upper right)
Settlement and cracking of the road surface as seen during the 2005 annual inspection. This pattern of damage to the road surface has been ongoing for the last several years, and was most recently noted during the borehole drilling and instrument installations in the spring of 2007 prior to the June 2007 inspection and photos.



Photo S10(A)-3 – June 2007 (lower left)
Facing south across the site.



Photo S10(A)-4 – June 2007 (lower right)
Another view facing south across the site.