


Overlays of various ages.
Typical pattern and extent of
cracking shown.



| | | | | |
|---------|--------------------------------------|--|-----------------|-----------|
| Client | Alberta Transportation | | Figure S10(C)-1 | |
| Project | Southern Region Geohazard Assessment | | Date: | Revision |
| | | | Jul-09 | |
| | S10(C) - HIGHWAY 762:02 | | Job No. | CG25309.B |
| | | | File No.: | |

