



Photo S10(A)-1 (upper left) – June 2005 – facing north across the settlement and cracking area in the southbound lane. This area was repaved in 2004 and the current cracking is in the same location and pattern noted in previous years.



Photo S10(A)-2 (upper right) – June 2005 – another view of area shown in Photo S10(A)-1. The damaged portion of the road is marked for repaving.



Photo S10(A)-3 (lower left) – June 2005 – facing south across site S10(A). The southbound lane has settled up to approximately 100 mm, apparently mostly during and after the heavy rains in June 2005.



Photo S10(A)-4 (lower right) – June 2005 – wider view across site, facing north. The pattern of the damage to the road indicates landslide movement down to the west (left).