



**Photo S10A - 1 (June 2012)** - Facing north from the south end of the site. An overlay was placed at the site in late 2011. Subtle cracking and settlement had formed through the overlay following similar extent as was observed in 2011 and in previous inspections.