



Photo S10A - 1 (May 2014) - Facing south from the north end of the site. Cracking and settlement had formed through the previous overlay following similar extent as was observed in 2012 and in previous inspections. The approximate extents of the main slide area within the road is outlined in red.



Photo S10A - 2 (May 2014) - Facing south at the new damage observed in the road surface, at the south end of the main slide area seen in the previous photo. The approximate extents of the newly observed damage is outlined in red.