



**Photo 8** (upper left) Site B  
Facing south across Site B. This site appeared to have been repaved only a few hours before the inspection.



**Photo 9** (upper right) Site B  
Another view facing south across Site B.



**Photo 10** (lower left) Site B  
West shoulder of the road in the repaved area. Notebook provides scale for the fresh asphalt thickness in this area.