



**Photo S10B-1** (upper left) – May 2004 – facing south across the July 2003 overlay at Site B. There is longitudinal cracking visible at the north end of the overlay (foreground of photo) but judged to be a pavement phenomenon rather than indicating geotechnical instability.



**Photo S10B-2** (upper right) – May 2004 – facing north. Another view of the longitudinal cracking at the north end of the July 2003 overlay at Site B.



**Photo S10B-3** (lower left) – May 2004 – general view facing south across the July 2003 overlay at Site B.



**Photo S10B-4** (lower right) – May 2004 – general view facing south across the July 2003 overlay at Site B.