



**Photo S10(B)-1** (upper left) – June 2005 – facing south across the portion of the southbound lane damaged by the instability caused by heavy rainfall in June 2005.



**Photo S10(B)-2** (upper right) – June 2005 – wider view facing south showing tension cracking and dropdown along the west shoulder to the north of the main failure area.



**Photo S10(B)-3** (lower left) – June 2005 – closer view of north flank of the main failure area.



**Photo S10(B)-4** (upper left) – June 2005 – deformation of slope face to west of road and tilted trees indicate that the overall toe of the failure extends to the west of the fence line.