



Photo S10(B)-1 (upper left) – May 2006 – facing south along the road. The area was repaved since the 2005 inspection. Minor longitudinal cracking visible in the repaved surface.



Photo S10(B)-2 (upper right) – May 2006 – facing south along the road. The area was repaved since the 2005 inspection. Compare with Photo S10(B)-3 (lower left) which shows the same area in June 2005.



Photo S10(B)-3 (lower left) – June 2005 – shows same area as Photo S10(B)-2, as it appeared in June 2005.



Photo S10 (B)-4 (lower right) – May 2006 – facing north along the road. The area was repaved since the 2005 inspection. Compare with Photo S10 (B)-5 (next page) which shows the same area in June 2005.



Photo S10(B)-5 (upper left) – June 2005 – shows the same area as Photo S10(B)-4, as it appeared in June 2005.