



**Photo 11** (left) Site C  
Facing north across Site C. This site had also been repaved a few hours before the inspection, therefore it was not possible to tell if further cracking or settlement had occurred since the May 2002 inspection.

**Photo 12** (right) Site C  
Same area as Photo 11, as seen during the May 2002 inspection.

