



Photo S10C-1 (upper left) – May 2004 – facing north across the July 2003 overlay at Site C. No recent cracking noted in the road surface.



Photo S10C-2 (upper right) – May 2004 – Another view of the July 2003 overlay at Site C, facing north. No recent cracking noted in the road surface.



Photo S10C-3 (lower left) – May 2004 – facing north along the west ditch downslope of the highway. Note the ponded water in the ditch. It appeared that the ponding of the water was due to the lack of ditch gradient through this area as well as groundwater seepage discharging from the toe of the slope.



Photo S10C-4 (lower right) – May 2004 – facing south along the west ditch below the highway. It is recommended that a weeping tile drain be installed in this ditch to pick up accumulated surface runoff and groundwater seepage from this area. The weeping tile should drain to the south.