



Photo S10(C)-1 (upper left) – June 2005 – facing north across recent cracking that extends in an arc from the east shoulder to the southbound lane. The center of the cracking is approximately 45 m north of the culvert below the road.



Photo S10(C)-2 (upper right) – June 2005 – facing northwest across the same area shown in Photo S10(C)-1. This view shows the settlement of the southbound lane.



Photo S10(C)-3 (lower left) – June 2005 – closer view of the north end of the cracking and settlement in the southbound lane.



Photo S10(C)-4 (lower right) – June 2005 – Ponded water in the west ditch to the north of the creek culvert following heavy rains in June 2005. The lack of positive drainage along this segment of the ditch has been identified as an issue in previous inspections.



Photo S10(C)-5 (above) – June 2005 – erosion damage in west ditch, south of the culvert.