



Photo 1 (top) – June 2009

Facing southbound along the east highway ditch adjacent to the cut slope, at the south end of the site. The rockfall debris is generally contained within the ditch, however some gravel sized pieces were on the pavement at the time of the June 2009 inspection.




Photo 2 (bottom) – June 2009

Facing northbound across the central and northern end of the site.



Photo 3 (top) – June 2009

Closer view of the accumulation and distribution of rockfall debris in the ditch at the south end of the site.