



**Photo S18-1 – May 2013**

A stitched panoramic image of the East Cut Slope taken from atop the West Cut. The curvature of the highway is exaggerated due to the image processing. Visible are the possible wedge, toppling, and block sliding failure modes supported by rock bolts.



**Photo S18-2 – May 2013**  
Facing northbound along the east ditch near the south end of the East Cut. Minor rock fall was observed in this area that did not appear to have landed on the road.



**Photo S18-3 – May 2013**  
Facing northbound from the top of the West Cut Slope. All rock fall was contained within the ditch.



**Photo S18-4 – May 2013**  
Standing at approximately the center of the site on the east side of the road facing northbound. Rock fall impacts were observed on the east road shoulder.