



Photo S19-1 – June 2007 (left)

Facing upstream along King Creek from the Highway 40 alignment.

Photo S19-2 – July 2005 (left)

Culvert inlet at toe of east embankment slope. A possible location for the inlet of a second culvert is marked. The second culvert could be installed to act as an “emergency drain” for creek flow in the event that the existing culvert is blocked by debris and water begins to impound on the upstream side of the highway embankment. Construction equipment can access this area via the old access trail from the King Creek picnic area parking lot on the south side of the creek channel.

