

(May 2002)

Photo 1 – Facing west along the downslope edge of the road through the slide area. The existing pile wall is located just to the left of the guardrail. Note how the guardrail has been displaced by settlement of the road, and the loss of ground downslope of the guardrail.



(May 2002)

Photo 2 – Toe of the landslide below the fenceline, approximately 150 m north of the road. The spreading of the landslide has caused colluvium to override the ground surface further downslope.



Alberta Transportation Southern Region Landslide Monitoring Program Spring 2002 Assessment Report

Site S2 - Priddis




Photo 4 – May 2001 photo of toe of slide approximately 150 m below road.



Alberta Transportation Southern Region Landslide Monitoring Program Spring 2002 Assessment Report

Site S2 - Priddis