



Photograph S20-1- Stitched photographs of cut slope taken from south side of the highway, with till soil layer and main debris cones marked.



Photograph S20-2 – Looking eastbound along the north ditch. Rock fall includes gravel to cobble sized rocks, with gravel on the paved shoulder and cobbles immediately adjacent to the paved surface. Boulder sized rocks are also present in the ditch, and during past inspections have been noted at positions along the edge of the pavement.



Photograph S20-3 – Looking westbound along the north ditch. Note the large boulders that have rolled down the main debris cones to within 2 m of the paved surface at the time of the June 2010 inspection.