



Photograph S20-1 – May 2013

Stitched photographs of cut slope taken from south side of the highway. Image is slightly distorted horizontally due to image processing.



Photograph S20-2 – May 2013

Looking eastbound along the north ditch. Rock fall includes gravel to cobble sized rocks, with gravel on the paved shoulder and cobbles immediately adjacent to the paved surface. Boulder sized rocks are also present in the ditch.



Photograph S20-3 – May 2013

Looking westbound along the north ditch. Ditch cleaning since the 2010 inspection has reduced the size of the debris cones.