



**Photo S22-1 – June 2012**  
Facing west (along the southbound lane) from the east end of the site. The recent milling work has exposed asphalt experiencing sub-grade failure (outlined in red). Milling may have caused the sub-grade failure.



**Photo S22-2 – June 2012**  
Facing west (along the southbound lane) from the east side of the site. The damage to the road surface is similar to that noted during past inspections.