



Photo S26-1 - (June 2012)
Facing south from the south end of Area A at the west road shoulder. Overlays have been placed at the damaged areas recently. Minor cracking was visible along the shoulder through the new overlay.



Photo S26-2 - (June 2012)
Facing south from the north end of Area A at the lower west slope. Fresh soil was exposed at the headscarp of one of the main lower slides.



Photo S26-3 - (June 2012)
Facing southeast from the north end of Area A at the seepage area on the east side of the highway. The ditch here was blocked with soil as a result of ongoing back slope movement.



Photo S26-4 - (June 2012)
Facing southwest from the lower west slope at Area B. Construction was underway during the inspection.



Photo S26-5 - (June 2012)
Facing south from the upper slope on the west side of Area B. Construction of the shear pile repair was underway during the inspection.