



Photo S26-1 - (May 2013)
Standing near the culvert outlet at Area A at the southern edge of the site looking towards the northwest. Numerous overlays and patches have created a drop-off on the downslope road shoulder northwest of the culvert.



Photo S26-2 - (May 2013)
Facing northwest from the south end of Area A at the west road shoulder. Overlays have been placed at the damaged areas in Fall 2012. Minor cracking and settlement was visible along the shoulder through the new overlay.



Photo S26-3 - (May 2013)
Facing south from the west side
of Area B.
No new cracking or settlement
was observed on the road
surface.



Photo S26-4 - (May 2013)
Facing south from the
upper slope on the west
side of Area B.
Construction of the shear
pile repair was complete in
Fall 2012. Vegetation has
begin to grow during 2013
inspections.