



Photo 1 – May 2002 photo of ditch along downslope edge of highway showing area where ditch liner was repaired in summer 2000. Repairs continue to function adequately.



(May 2002)

Photo 2 – Cracking on north shoulder of road adjacent to SI #4 (blue casing on left of photo). The cracking appeared to be longitudinal, but could possibly be associated with continued downslope movement at approximately 2.7 m depth in SI #4.



(May 2002)

Photo 3 – Close up view of cracking on north shoulder of road adjacent to SI #4.