

Photo S30-1 – June 2008

Facing north towards the gabion wall from across the valley. The segment of the wall that collapsed in 2007 and the undermined areas are noted.




Photo S30-2 – June 2012

Facing north towards the gabion wall from across the valley from the same location as Photo S30-1. The gabion baskets from the collapsed segment of the wall have been removed. The undermining at the base of the wall has expanded.



Photo S30-3 – June 2012
Undermining at the base of the eastern end of the gabion wall. There was no flow at the time of the site inspection. The undermining has expanded considerably since 2008.



Photo S30-4 – June 2012
Gullying and surface erosion along the downslope edge of the highway, above the collapsed segment of the wall. The geogrid within the road embankment continues to support the highway, but the loss of erosion protection provided by the gabion wall has allowed surface erosion to continue and retrogress back to the edge of the guardrail since the 2008 inspection.