



Photo S3-1 (upper left) – June 2005 – Facing west across the S3 – Cochrane site. The fenceline has been displaced and stretched tight as a result of ongoing slope movement. The visible headscarp cracking of this slope movement is approximately 1 m upslope of SI#3A, which is located just off the left edge of the photo.



Photo S3-2 (lower left) – June 2005 – tension crack showing recent movement around the north flank of the slope movement shown in Photo S3-1. Field notebook for scale.



Photo S3-3 (lower right) – June 2005 – shallow sloughing on slope to the north of the road. This particular feature was new this year and most likely developed during heavy rainfall in mid to late June 2005.



Photo S3-4 (upper left) – June 2005 – facing west along the road. Large cracks in the shoulder developed between the time of instrument readings in May 2005 and the site inspection in late June 2005.



Photo S3-5 (lower left) – June 2005 – closer view of recent cracking in westbound shoulder. Field notebook for scale.



Photo S3-6 (lower right) – June 2005 – facing east along the road with recent cracking visible in the shoulder.