



**Photo S32-1 – June 2012**  
Facing south towards the east ferry ramp. The ferry guide wire support tower is just out of the frame on the left side of the photo. This area appears mostly unchanged since the previous inspection.



**Photo S32-2 – June 2012**  
Facing south towards the area near the ferry sign where fresh bank retrogression was observed.



**Photo S32-3 – June 2012**  
Facing north over the main landslide area. Some evidence of fresh sliding was observed but the main crest is mainly unchanged from the 2010 inspection.