



Photo 1 – June 2009 (top)
Facing downstream along the creek channel towards the highway crossing. Note the lack of surface flow in the channel.



Photo 2 – June 2009 (bottom)
Facing upstream along the creek channel from the same location that Photo 1 was taken from.