



Photo 1 (top) – June 2009

The ponded water upstream of the highway culverts is at approximately the same level as was observed in the fall of 2008.

Photo 2 (left) – June 2009

The culvert inlets appear to be in the same condition as seen during the Fall 2008 inspection.




Photo 3 – June 2009

The culvert outlets were both discharging water without apparent obstruction. The 900 mm diameter culvert remains separated at the top between segments.



Photo 4 – June 2009

Close-up view of the separated segments of the 900 mm diameter culvert.