



Photo 1 – June 2009

Looking northeast along the edge of the road. Erosion gully has encroached onto the shoulder and is within 1 m of the tire tracks on the road surface. Stakes mark the June 2009 upslope extent of the gully for future comparison.



Photo 2 – June 2009

Looking southwest along the edge of the road (prior to the installation of the reference stakes visible in Photo 1). Surface runoff from the road is channelled into the head of the gully.



Photo 3 – June 2009
Another view of the erosion gully encroaching onto the road surface.



Photo 4 – June 2009
The erosion gully from near the creek level.



Photo 5 – June 2009

Bedrock exposure upstream
from the erosion gully with
bedrock striking at 30/210° and
dipping at 10 to 20° towards
the northwest.