



**Photograph 1 – Stitched panorama of Km 15.8 Site taken from the slope above (west of) the site. The cracks in the road surface are marked for clarity. The apparent curvature of the road is due to the photograph stitching software and is not realistic.**



**Photograph 2 – Top Left – Cracks in the road surface at Km 15.8 Site.**

**Photograph 3 – Bottom Left – Looking northbound at cracks in the road surface at Km 15.8 Site.**

**Photograph 4 – Top Right – Perforated drainage pipe outlet in the east ditch at Km 15.8 Site.**



**Photograph 5 – Stitched panoramic of Km 15.8 Site taken from the slope above the site. The cracks in the road surface are marked for clarity.**