



**Photo S38-1 (June 2012)**

Facing south from the east side of the highway. The site had undergone recent patch / overlay work. Very minor cracking was coming through the new pavement in previously noted areas.



**Photo S38-2 (June 2012)**

Facing west upslope from the fenceline on the east side of the highway. Shallow sliding was noted in this area of the slope near the north end of the site and a fresh scarp is marked in red on the photo. The scarp had 200 mm aperture and 100 mm of down-drop.





**Photo S38-3 (June 2012)**

Facing west upslope from below the fenceline on the east side of the highway.



**Photo S38-4 (June 2012)**

View of a subtle scarp (marked in orange), which was observed near the downslope (east) highway shoulder at the south end of the site.