



Photo S38-1 (May 2013)
Facing south from the east side of the highway. Minor cracking and settlement was visible through the previous overlay.



Photo S38-2 (May 2013)
Sliding near the north end of the site. The main scarp is marked in orange on the photo.