



**Photo S39-1 - (June 1, 2011)**

Facing westbound towards the cracks on the road surface. The landsliding in the valley slope is visible on the right hand side of the photo, just downslope of the highway.



**Photo S39-2 - (June 20, 2012)**

Facing westbound towards the cracks on the road surface. The extent of the cracking has slightly increased towards the east since 2011.



**Photo S39-3 (June 20, 2012)**

Facing upslope towards the upper portion of the landslide mass on the valley slope below the highway. The approximate location of the overall landslide headscarp is marked, as well as the point where the headscarp and gully erosion has reached the guardrail as of June 2012.



**Photo S39-4 (June 20, 2012)**

Facing southeast from the west flank of the landslide at the main headscarp area. This area appeared mostly unchanged since the 2011 inspection.