



**Photo S39-1 - (June 1, 2011)**

Facing westbound towards the cracks on the road surface.



**Photo S39-2 - (May 28, 2013)**

Facing westbound towards the cracks on the road surface. The extent of the cracking had remained similar to 2012. The repaired cracks at the western end of the site have also re-opened.



**Photo S39-3 (May 28, 2013)**

Facing upslope towards the upper portion of the landslide mass on the valley slope below the highway. The approximate location of the overall landslide headscarp is marked, as well as the point where the headscarp and gully erosion has reached the guardrail as of May 2013.



**Photo S39-4 (May 28, 2013)**

Facing west from the east flank of the landslide at the main headscarp area. This area appeared mostly unchanged since the 2012 inspection.