



Photo 1 – View of downslope edge of the road showing the proximity of the landslide scarp to the guardrail (May 2002).



Photo 2 – Downslope edge of road as seen during the May 2001 inspection.



(May 2002)

Photo 3 – Recent gullying and piping in the exposed soils on the landslide blocks immediately downslope of the road.



(May 2002)

Photo 4 – Facing southwest across the landslide area. Note the new SI 2002-1 installed in the upslope road ditch in order to monitor for additional/deep-seated movements retrogressing above the road.

