



Photo S5-1 (upper left) – June 2005 – facing east across the shallow slumping area that is undermining the guardrail along the downslope edge of the road. Possible additional cracking since the 2004 inspection was noted but the overall state of the slumping did not appear to have changed significantly.



Photo S5-2 (upper right) – June 2005 – facing west across the shallow slumping area below the road.



Photo S5-2 (lower left) – June 2005 – facing east along eastbound lane. Note the settlement in the shoulder next to the guardrail.



Photo S5-4 (left) – shallow slumping on slope downslope of the road.



Photo S5-5 (right) – facing west along road. No new cracking visible since the last annual inspection.