



Photo 1

**Looking south away from Hwy 2:50 junction**

- Drift Pile River running north (on left of photo) (on east side) beside local road
- On left (east) side, top of eroded bank at about 7m setback to edge of local road
- On right (west) side, edge of local road is offset about 14m from a dugout pond



Photo 2

**Looking south upstream from top of setback**

- A meander scour bank is being eroded to encroach towards the roadway
- Roadway on right side of photo

*Note: Photos taken on July 17, 2008*



**Photo 3**

- Looking north towards junction Hwy 2:50**
- Drift-Pile River on east side (right of photo)
  - Dugout pond on west side (left of photo)



**Photo 1**  
Looking east at river bank scour location



**Photo 2**  
Looking north at scour location



**Photo 3**  
Looking east (downstream) at additional slumps/scours along south bank of Driftpile River (right hand side of photo)

**Note: Photos taken on April 22, 2009**



**Photo 4**  
**Looking northwest at scour location**  
- Crest of scour within 3 m of edge of roadway  
- Area barricaded and demarcated to notify motorists of reduced setback distance and to minimize public access into area



**Photo 5**  
Looking south at undeveloped forest area on south side of Township Road 735A, opposite of scour location

**Note: Photos taken on April 22, 2009**