



Photo 1

Looking east downstream

Scouring bank of the meandering Drift Pile river channel
has effected this bowl location of retrogression of slumping

Shape of escarpment seems no obvious deterioration from previous year.

Bowl width (about 12m), depth (about 10m inland towards roadway), setback (about 3m from scarp to road edge)

Note: Photos taken on May 2010

**SH 29a
Page 1 of 2**



Photo 2
Another view of escarpment bowl



Photo 2a
Another view of escarpment bowl

Note: Photos taken on May 2010