

Photo 1: East crack (note west crack in distance).




Photo 2: Tension crack and toe bulge, south of Highway 43.



Photo 3: Toe bulge on south side of highway, facing east.



Photo 4: Erosion along outside shoulder of eastbound lanes.



Photo 5: Subdrain outlet and debris accumulation in half-round culvert.



Photo 6: Debris collecting at culvert outlet at approximately station 1+600.



Photo 7: Crack in paved trail above bin wall reflecting through seal.