



**Photo #1** Looking east at the highway surface. Existing patch defines the limits of the repair



**Photo #2** Looking east from the western flank of the landslide at a reflective diagonal crack in the highway EBL



**Photo #3** Looking east from the middle of the landslide at longitudinal reflective crack on the highway EBL



**Photo #4** Looking west from the eastern limit of the landslide at a diagonal reflective crack; note the dip on the highway EBL surface near the western limit of the patched area



**Photo #5** Looking east at open longitudinal cracks on the highway WBL



**Photo #6** Looking west at additional set of longitudinal cracks on the highway WBL