



Photo 1.

June 2008

View looking south along Hwy 744, showing the lay-by, starting at the guardrail at the left of the picture.



Photo 2.

June 2008

Slide 1 at the north end of the site. There is no fresh slide movement visible from the crest of the slope. This slide area was repaired by re-grading and improving drainage some time prior to 2004.



Photo 3.

June 2008

Looking down-slope (eastwards) at Slide 1. No significant changes since the inspection in 2007. Note the water in the sag pond above the Heart River.



Photo 4.

June 2008

Looking south along the backscarp of Slide 2. The backscarp shows fresh movement, and has expanded laterally, but has only retrogressed by around 20 cm since the last inspection in 2007. The indistinct scarp on the south side of the slide (circled) has a roughly 0.75 m vertical offset.



Photo 5.

June 2008

Looking down-slope at Slide 2. There is fresh movement in the slide bowl, and water ponded in the debris.



Photo 6.

June 2008

Looking northwards at Slide 2 showing fresh debris in the slide bowl.



Photo 7.

June 2008

Backscarp of Slide 3 – no fresh movement at the backscarp, but the area of fresh movement noted down-slope is still there.



Photo 8.

June 2008

Backscarp of Slide 4 with fresh movement since the 2007 inspection. The backscarp is roughly 5 m high and 17 m wide, and appears to have retrogressed by up to 0.5 m.



Photo 9.

June 2008

Looking downhill from
the backscarp of
Slide 4.