



Photo 1 - Looking east along the highway over the Grimms Creek site area.
Note the ACP patches and the dip in the highway.



Photo 2 – Looking east along the downstream embankment and guardrail.



Photo 3 - Looking southeast at the culvert inlet area.



Photo 4 - Looking east at a 10 m long x 1.5 m deep erosion gully that has enlarged on the east side of the channel in front of the culvert inlet.



Photo 5 - Looking north along the eroded channel upstream of the culvert inlet.



Photo 6 – Looking southwest across the downstream highway embankment at the previous culvert outlet area.



Photo 7 - Looking northwest at the new culvert outlet. It is about 50% full of sediment.



Photo 8 - Looking west along the south guardrail that is damaged.