


SITE NUMBER AND NAME C38 H14:16 Culvert Erosion		HIGHWAY & KM 51.5	PREVIOUS INSPECTION DATE August 4, 2006	INSPECTION DATE May 14, 2007
LEGAL DESCRIPTION NE 5-45-01-W4	NAD 83 COORDINATES		RISK ASSESMENT PF: 9 CF: 2 TOTAL: 18	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Culvert Erosion	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Proposed Repair in Summer 2007	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion	X		Slope erosion is on-going.	X	
Seepage		X			X
Culvert Distress	X				X

COMMENTS
Refer to previous reports and attached photographs.
Slope erosion is on-going; however, the highway is unaffected.