


SITE NUMBER AND NAME C38 H14:16 Culvert Erosion		HIGHWAY & KM 51.5	PREVIOUS INSPECTION DATE July 27, 2007	INSPECTION DATE June 25, 2008
LEGAL DESCRIPTION NE 5-45-01-W4	NAD 83 COORDINATES N 5855725 E 560300		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: None	INSPECTED BY: 
LAST READING DATE:	
PRIMARY SITE ISSUE: Culvert Erosion	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Culvert was extended and erosion protection was placed in the summer of 2007.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion	X		Slope is eroding under matting in some locations. However, site is well away from roadway.	X	
Seepage		X			X
Culvert Distress	X		Culvert extended and riprap placed.		X

COMMENTS
Refer to previous reports and attached photographs.

Site C38 H14:16 Culvert Erosion
June 25, 2008



Site C38 H14:16 Culvert Erosion
June 25, 2008





Site C38 H14:16 Culvert Erosion
June 25, 2008



