


SITE NUMBER AND NAME <b>C29 H17:08 Meridian Pit</b>		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 19, 2004	INSPECTION DATE <b>June 25, 2008</b>
LEGAL DESCRIPTION NE/SE 26-53-01-W4	NAD 83 COORDINATES N 5939566 E 565036		RISK ASSESMENT PF: 1 CF: 1 TOTAL: <b>1</b>	

SUMMARY OF SITE INSTRUMENTATION:  Inclinometers adjacent to gabion structure  LAST READING DATE: Unknown (Read by Sask Highways)	INSPECTED BY: 
PRIMARY SITE ISSUE: Unsafe embankment (removed Fall 2003), channel erosion, damage to gabion structure.	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Gabion structure repaired and stilling basin constructed 2004.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion	X		Repaired gabion structure appears to be performing well.		X
Seepage		X			X
Culvert Distress		X			X

COMMENTS
Refer to previous reports and attached photos.

Site C29 H17:08 Meridian Pit Issues  
June 25, 2008





Site C29 H17:08 Meridian Pit Issues  
June 25, 2008



