


**CENTRAL REGION
GEOHAZARDS RISK ASSESMENT
SITE INSPECTION FORM**

SITE NUMBER AND NAME C5 H27:10 Cream Coulee		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 21, 2003	INSPECTION DATE May 18, 2004
LEGAL DESCRIPTION SW 17-31-22-W4	NAD 83 COORDINATES N 5724120 E 354750	RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1		

SUMMARY OF SITE INSTRUMENTATION: 1 Standpipe piezometer – measured water level 12.83 m BTOP (water elevation 86.23 m) and is consistent with previous water level measurements. LAST READING DATE: May 18, 2004	INSPECTED BY: 
PRIMARY SITE ISSUE: Embankment failure – repaired October 2003	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Embankment re-constructed October 2003	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress					
Slope Movement		X			
Erosion	X		Minor erosion is occurring close to culvert inlet.		
Seepage					
Culvert Distress		X			

COMMENTS
Refer to previous inspection reports for site history and attached photos.
Repaired area has no signs of cracks and grass is starting to grow.
The minor erosion should be repaired by re-grading the area appropriately and reseeding. A small section of riprap or erosion protection matting may be required to protect the area while the grass is growing.
It is recommended that this site be deleted from the GeoHazard Monitoring Program.

