

CENTRAL REGION GEOHAZARDS RISK ASSESMENT SITE INSPECTION FORM



1

INSPECTED BY:

HIGHWAY & KM PREVIOUS SITE NUMBER AND NAME INSPECTION DATE INSPECTION DATE C5 H27:10 Cream Coulee May 27, 2005 May 18, 2004 LEGAL DESCRIPTION NAD 83 COORDINATES **RISK ASSESMENT** SW 17-31-22-W4 N 5724120 PF: TOTAL: E 354750 1 CF: 1

SUMMARY OF SITE INSTRUMENTATION:

LAST READING DATE:

PRIMARY SITE ISSUE: Embankment failure - repaired October 2003

APPROXIMATE DIMENSIONS:

DATE OF ANY REMEDIAL ACTION: Embankment re-constructed October 2003

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION YES NO	
Pavement Distress					
Slope Movement					
Erosion					
Seepage					
Culvert Distress					
COMMENTS					
Refer to previous inspection reports for site history and attached photos.					
Repaired area has no signs of cracks and grass is starting to grow.					
It is recommended that this site be deleted from the GeoHazard Monitoring Program.					



