


SITE NUMBER AND NAME <b>C21 H576:02 Settlement</b>		HIGHWAY & KM	PREVIOUS INSPECTION DATE June 20, 2011	INSPECTION DATE <b>June 14, 2012</b>
LEGAL DESCRIPTION 15-29-17-W4	NAD 83 COORDINATES N 5,703,395 E 408,240		RISK ASSESMENT PF: 1 CF: 1 TOTAL: <b>1</b>	

SUMMARY OF SITE INSTRUMENTATION: 1 Slope inclinometer, 3 Pneumatic Piezometers (2001) - destroyed	INSPECTED BY: 
LAST READING DATE: 2001	
PRIMARY SITE ISSUE: Settlement due to internal erosion	
APPROXIMATE DIMENSIONS: about 100 m long over full width of highway.	
DATE OF ANY REMEDIAL ACTION: Gravel fill and perforated drains added in 2010. Additional gravel fill placed in 2011 and 2012.	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X	Gravel road. Grade has been restored by gravel fill placement.		
Slope Movement		X			
Erosion	X				
Seepage	X				
Culvert Distress	X				
<b>COMMENTS</b>					
Delete from geohazard program unless settlement continues.					

















