


SITE NUMBER AND NAME <b>C39 H576:02 Slide</b>		HIGHWAY & KM 2.5	PREVIOUS INSPECTION DATE Oct 20, 2006	INSPECTION DATE <b>June 1, 2007</b>
LEGAL DESCRIPTION 13-29-20-W4	NAD 83 COORDINATES N 57004150 E 382250		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION:  None	INSPECTED BY:  
LAST READING DATE:	
PRIMARY SITE ISSUE: Slope instability	
APPROXIMATE DIMENSIONS:	
DATE OF ANY REMEDIAL ACTION: Slope repaired in October 2006	

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X	Slope reinstated with reinforced gravel. No further movement observed.		X
Erosion		X			X
Seepage		X			X
Culvert Distress		X			X

<b>COMMENTS</b>
Refer to previous reports and attached photos.

Site C39 H576:02 Slide  
June 1, 2007



Site C39 H576:02 Slide  
June 1, 2007



Site C39 H576:02 Slide  
June 1, 2007

