


SITE NUMBER AND NAME C08 H597:02 Blackfalds		HIGHWAY & KM	PREVIOUS INSPECTION DATE May 19, 2010	INSPECTION DATE May 18, 2011
LEGAL DESCRIPTION NE 9-39-26-W4	NAD 83 COORDINATES N 5803030 E 317080		RISK ASSESMENT PF: 1 CF: 1 TOTAL: 1	

SUMMARY OF SITE INSTRUMENTATION: 1 SI operational, but is on north side of highway outside of slide area. 2 standpipe piezometers are operational.		INSPECTED BY: 
LAST READING DATE: Piezometers read June 4, 2009.		
PRIMARY SITE ISSUE: Slope Instability		
APPROXIMATE DIMENSIONS: 80 m wide and extended about 25 m down the slope		
DATE OF ANY REMEDIAL ACTION: Remediation performed between June 24 and July 3, 2007 using launched soil nails.		

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION	NOTICABLE CHANGE FROM LAST INSPECTION	
	YES	NO		YES	NO
Pavement Distress		X			X
Slope Movement		X			X
Erosion		X			X
Seepage		X			X
Culvert Distress		X			X

COMMENTS
Refer to attached photos, previous inspection reports and 2007 construction report for site history. MCI to monitor – remove from Geohazard program

