

CENTRAL REGION GEOHAZARD RISK ASSESMENT SITE INSPECTION FORM



211211,1212-011-01,1-0111,1								
SITE NUMBER AND NAME		HIGHWAY & KM	PREV			INSP	ECTION DAT	E
C44 H760:02 Slide			INSPE	ECTIO	N DATE		luna 22 2	010
C44 H760:02 Slide		3	June	26, 2	2008	J	lune 23, 2	.010
LEGAL DESCRIPTION	NAD 83 COORDI	INATES	RISK	(ASS	SESMEN'	Τ		
NE 19-48-5-W4	N 5890109	E 519390	PF:	1	CF:	1	TOTAL:	1

SUMMARY OF SITE INSTRUMENTAT	ION:	INSPECTED BY:
		FNGINES
None		N. RAPP
110110		
LAST READING DATE:		छिठ्ठहुँचा 🖊
LAST READING DATE.		
PRIMARY SITE ISSUE:		
	Slope Failure	
APPROXIMATE DIMENSIONS:	·	
DATE OF ANY REMEDIAL ACTION:	Slide area excavated and reinstated with rein	nforced gravel August 2007.

ITEM	CONDITION EXISTS		DESCRIPTION AND LOCATION		NOTICABLE CHANGE FROM LAST INSPECTION				
	YES	NO		YES	NO				
Pavement Distress		Х	A few reflective cracks near shoulder in asphalt patch.	Х					
Slope Movement		X	Stabilized slope is performing well. No evidence of slope movement is apparent.		X				
Erosion		Χ			X				
Seepage		Х			X				
Culvert Distress		Х			Х				
COMMENTS									
Refer to attached photos and previous reports.									



Page 1 of 4



Page 2 of 4



